Release Notes for DrayTek Vigor 3910 (UK/Ireland)

Firmware Version	3.9.1.3 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	6 th February 2020
Release Date	14 th February 2020
Revision	1286_88265
Applicable Models	Vigor 3910
Locale	UK & Ireland Only

New Features

(None)

Improvements

- 1. WAN port status mechanism improved
- 2. Handling of incorrect router configuration improved
- 3. Dial-in IPSec Aggressive VPN connection could not reconnect after a reboot
- 4. SSL VPN LAN to LAN did not forward packets with MTU 1395-1400
- 5. Improved MSS (Maximum Segment Size) for SSL VPN
- 6. Improved management of Hardware Accelerated sessions when WAN disconnects

Known	Issues
-------	--------

(None)

Firmware File Types

The file name of the firmware controls which upgrade type is performed.

If the file name is unchanged (e.g. xxxx.all) then the upgrade will just upgrade the firmware, whereas renaming the firmware to a .rst extension will wipe all settings back to factory defaults when upgrading the firmware.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the router's system maintenance menu.

To upgrade firmware, select 'firmware upgrade' from the router's system maintenance menu and select the correct file. Ensure that you select the ALL file <u>unless</u> you want to wipe out your router's settings back to factory default.



Manual Upgrade

If you cannot access the router's menu, you can put the router into 'TFTP' mode by holding the RESET whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier and recommended – this manual mode is only needed if the web interface is inaccessible.

Firmware Version	3.9.1.2 (Initial Release Firmware)
Release Type	Initial Release
Build Date	4 th December 2019
Release Date	11 th December 2019
Revision	1217_87018
Applicable Models	Vigor 3910
Locale	UK & Ireland Only

First Firmware Release for this model

New Features	5
(None)	

<u>Improvements</u>

(None)

Known Issues

(None)

[END OF FILE]