

Release Notes for DrayTek VigorAP 912c (UK/Ireland)

Firmware Version	1.3.3
Release Type	Regular – Upgrade recommended when convenient
Release Date	31 st March 2020
Build Date	6 th March 2020
Revision	11701
Applicable Models	VigorAP 912c
Locale	UK Only

New Features

1. Add the options of Access List and Allow management from WLAN on [System Maintenance] > [Management]
2. Add the option for enabling / disabling TLS/SSL Encryption Setup on [System Maintenance] > [Management]

Improvements

1. [Wireless LAN] > [Station List] window enlarged for the convenience of viewing device information
2. Change the colour of the index number on [Application] > [Schedule]
3. Mesh network stability improvements
4. Improvements to DHCP Server

Known Issues

(None)


Firmware File Types

The file name of the firmware controls which upgrade type is performed. If the file name is unchanged (e.g. xxxx.all) then the upgrade will just upgrade the firmware, whereas renaming the firmware to a .rst extension will wipe all settings back to factory defaults when upgrading the firmware.

Upgrade Instructions

It is recommended that you take a configuration backup prior to upgrading the firmware. This can be done from the AP's system maintenance menu.

To upgrade firmware, select '*firmware upgrade*' from the AP's system maintenance menu and select the correct file. The access point will perform the upgrade and automatically reboot once this completes.



Manual Upgrade

If you cannot access the AP's menu, you can put the AP into 'TFTP' mode by holding the FACTORY RESET button whilst turning the unit on and then use the Firmware Utility. That will enable TFTP mode. TFTP mode is indicated by all LEDs flashing. This mode will also be automatically enabled by the router if there is a firmware/settings abnormality. Upgrading from the web interface is easier.

Firmware Version	1.3.2 (Formal Release)
Release Type	Initial Release
Release Date	30 th January 2020
Build Date	7 th January 2020
Revision	11442
Applicable Models	VigorAP 912c
Locale	UK Only

First Firmware Release for this model

Known Issues

(None)

[END OF FILE]