

Release Notes for DrayTek VigorSwitch FX2120 (UK/Ireland)

Firmware Version	3.9.11 (Formal Release)
Release Type	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Build Date	4 th August 2026
Release Date	7 th September 2026
Build Revision	242fcab
Applicable Models	VigorSwitch FX2120
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. Improved OpenSSL security
2. Improved the TR-069 configuration page
3. Improved the password strength checking method

Notes

1. STP (Spanning Tree Protocol) has been enabled by default, which may affect the time it takes for ports to come up
-

Firmware Version	3.9.10 (Formal Release)
Release Type	Important – Review release notes and upgrade if the changes affect your system stability, performance, or security
Build Date	12 th June 2026
Release Date	30 th June 2026
Build Revision	e17971d
Applicable Models	VigorSwitch FX2120
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. Improved the CGI security
2. Updated OpenSSL from v3.6.0 to v3.6.3, incorporating the latest security patches and fixes
3. Added support for including the device hostname in DHCP Option 12 when sending DHCP requests
4. Corrected an issue where a DHCP Server IP interface with the Pool Count set to 1021 generated an error and could not be saved
5. Corrected an issue where the switch rebooted when clearing the Protected Host Table while the MAC table contained a large number of entries
6. Corrected an issue where stale MAC/ARP entries remained on the L3 switch after an HA VIP failover, causing traffic to be forwarded to the previously active node
7. Corrected an issue where intermittent L3 VLAN routing failures caused end devices to lose connectivity under high network load when using the switch as their default gateway

Notes

1. STP (Spanning Tree Protocol) has been enabled by default, which may affect the time it takes for ports to come up

Firmware Version	3.9.9 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	16 th January 2026
Release Date	13 th March 2026
Build Revision	133954f
Applicable Models	VigorSwitch FX2120
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. The syslog format prevented VigorACS from collecting logs correctly
2. VLAN interfaces were inaccessible from a static routed network
3. Applying an empty port description profile in Central Management did not clear the existing switch settings

Notes

1. STP (Spanning Tree Protocol) has been enabled by default, which may affect the time it takes for ports to come up
-

Firmware Version	3.9.7 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	26 th February 2025
Release Date	9 th May 2025
Build Revision	489852f
Applicable Models	VigorSwitch FX2120
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. Improvements to the Web GUI security
2. Improvements to the DNS domain registration with TR-069 service

Firmware Version	3.9.6 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	30 th December 2024
Release Date	5 th February 2025
Build Revision	e2ed6cd
Applicable Models	VigorSwitch FX2120
Locale	UK & Ireland Only

New Features

(None)

Improvements

1. The "UDPConnectionRequestAddress" parameter added for STUN server configuration
2. The Host Name field added (available when VigorSwitch is DHCP Client)
3. Improvements to the QoS mechanism
4. Improvements to the group display for ACLs
5. Fix an issue with the DHCP server configuration
6. Improvements to the SNMP probing
7. Optimizing of the layout of the WUI
8. Improvements to the TR-069 parameter related issues
9. Corrected issue with port Linkup rate
10. Corrected a priority issue concerning DHCP snooping and access control lists (ACLs)

Firmware Version	3.7.4 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	12 th July 2022
Release Date	31 st January 2023
Build Revision	f1ce7b3
Applicable Models	VigorSwitch FX2120
Locale	UK & Ireland Only

New Features

1. Support added for Auto Fibre Media Type

Improvements

1. Improved the (10G) port link aggregation that did not work after the reboot

Firmware Version	3.7.3 (Formal Release)
Release Type	First Firmware Release
Build Date	13 th May 2022
Release Date	31 st August 2022
Build Revision	cb8457f
Applicable Models	VigorSwitch FX2120
Locale	UK & Ireland Only

First Firmware Release

[END OF FILE]