Release Notes for DrayTek VigorSwitch P1085 (UK/Ireland)

Firmware Version	2.6.7 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	29 th January 2021
Release Date	16 th April 2021
Build Revision	1959
Applicable Models	VigorSwitch P1085
Locale	UK & Ireland Only

New Features

(none)

Improvements

1. Updated MyVigor authentication method

Firmware Version	2.6.6 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	28 th October 2020
Release Date	12 th November 2020
Build Revision	1952
Applicable Models	VigorSwitch P1085
Locale	UK & Ireland Only

New Features

(none)

Improvements

- The Switch's self-signed certificate will change upon upgrade for compatibility with new browser certificate requirements.
 Starting from September 2020, many client OS & browsers will limit publicly trusted TLS server certificate lifetime to 398 days or less, and connections will be rejected if certificates exceed this. This firmware patch will automatically re-sign all self-signed certificate lifetimes
- to 395 days (was 2 years or longer in older versions)
- 2. Support for statistics/counters information for each port on Status page
- Support for editing the port number for HTTP management on [System Maintenance] > [Access Manager]

Firmware Version	2.6.4 (Formal Release)
Release Type	Regular – Upgrade recommended when convenient
Build Date	16 th July 2020
Release Date	13 th August 2020
Build Revision	1909
Applicable Models	VigorSwitch P1085
Locale	UK & Ireland Only

New Features

(none)

Improvements

- 1. Loop Protection Per Port Settings added
- 2. [VLAN Management] > [Interface Settings] dashboard panel added
- 3. Improved compatibility between TR-069 and VigorACS

Firmware Version	2.6.0 (Formal Release)
Release Type	First Firmware Release
Build Date	2 nd February 2020
Release Date	15 th June 2020
Build Revision	1763
Applicable Models	VigorSwitch P1085
Locale	UK & Ireland Only

First Firmware Release

[END OF FILE]