

## **Release Notes for DrayTek VigorSwitch P2280x (UK/Ireland)**

Firmware Version	2.6.4 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	24 <sup>th</sup> July 2020
Release Date	28 <sup>th</sup> August 2020
Build Revision	1912
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

### **New Features**

1. DHCP Relay is now available in [Switch LAN] > [DHCP Server / Relay] section

### **Improvements**

(none)

Firmware Version	2.6.3.1 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	27 <sup>th</sup> July 2020
Release Date	31 <sup>st</sup> July 2020
Build Revision	1913
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. The SYS LED would not light up after turning on the switch

Firmware Version	2.6.3 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	19 <sup>th</sup> June 2020
Release Date	10 <sup>th</sup> July 2020
Build Revision	1889
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Improved compatibility between TR-069 and VigorConnect

Firmware Version	2.6.2 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	22 <sup>nd</sup> April 2020
Release Date	15 <sup>th</sup> May 2020
Build Revision	1834
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Loop Protection Per Port Settings added
2. [VLAN Management] > [Interface Settings] dashboard panel added
3. Improved compatibility between TR-069 and VigorACS
4. QoS Basic Mode with Ingress Trust Mode CoS/802.1p-DSCP could not be used

Firmware Version	2.6.1 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	16 <sup>th</sup> March 2020
Release Date	03 <sup>rd</sup> April 2020
Build Revision	1810
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

### **New Features**

1. DHCP server can be configured on [Switch LAN] > [DHCP Server]

### **Improvements**

(none)

Firmware Version	2.6.0 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	22 <sup>nd</sup> January 2020
Release Date	2 <sup>nd</sup> March 2020
Build Revision	1763
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

### **New Features**

(none)

### **Improvements**

1. Vigor ACS compatibility updated
2. Improvements of IP Conflict Detection feature
3. Support for VLAN interface on [ONVIF Surveillance] > [Topology] page

Firmware Version	2.5.1 (Formal Release)
Release Type	<b>Regular</b> – Upgrade recommended when convenient
Build Date	06 <sup>th</sup> December 2020
Release Date	10 <sup>th</sup> January 2020
Build Revision	1688
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

### **New Features**

1. Support for TLS 1.3
2. Support for VigorConnect management

### **Improvements**

1. New TR069 parameters added
2. Improvements to IP Conflict Prevention
3. Improved interoperability of ONVIF Camera Management with Milesight IP cameras

Firmware Version	2.5.0 (Formal Release)
Release Type	<b>First Firmware Release</b>
Build Date	5 <sup>th</sup> May 2019
Release Date	2 <sup>nd</sup> August 2019
Build Revision	1421
Applicable Models	VigorSwitch P2280x
Locale	UK & Ireland Only

**First Firmware Release**

**[END OF FILE]**